






	Neu-Anbau	Villa
Typ1	22	11
Typ2	9	0
Typ3	10	4
Typ4	24	0
Typ5	193	0
Typ6	8	0
Typ7	11	0
Typ8	12	0
Typ9	0	1
Typ10	0	52
Typ11	0	5
Typ12	0	7
Typ13	0	2
Typ14	0	2
Typ15	0	3
Typ16	0	40
Typ17	0	9
Typ18	0	13
Typ19	0	8
Typ20	0	6
Typ21	0	2
Typ22	12	0
Typ23	3	0
Gesamt	304	165
469		

Altleuchten Lagerung



	Altleuchten einlagern	Leuchtmittellentnahme	Entsorgung
Typ1	4	29	29
Typ2	2	7	7
Typ3	4	20	10
Typ4	4	20	20
Typ5	5	376	188
Typ6	4	4	4
Typ7	4	14	7
Typ8	6	6	6
Typ9	1	0	0
Typ10	5	94	47
Typ11	5	0	0
Typ12	2	3	3
Typ13	2	0	0
Typ14	2	0	0
Typ15	3	0	0
Typ16	10	30	30
Typ17	0	0	0
Typ18	13	0	0
Typ19	2	6	2
Typ20	6	0	0
Typ21	2	0	0
Typ22	2	10	10
Typ23	0	0	0
Gesamt	88	619	363